

68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



68 Herndon. Front door.
5-20-25

68 Herndon Dr., Evansville, IN 47711


Scope of Service - Photos



68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos

68 Herndon. 5-20-25.
Soffit & fascia



68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



68 Herndon. 5-20-25.
Windows

68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



68 Herndon. 5-20-25.
Bad windows


68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos



Basement window.
5-20-25. 68 Herndon

68 Herndon Dr., Evansville, IN 47711

Scope of Service - Photos

