Form Information

Form Name:	**IHCDA | BLN Pre-Bid Survey Results**
Submission Date:	Aug 28, 2018 4:21:06 PM EDT

General Parcel Survey Information

Date of Survey	Aug 28, 2018
Name of Surveyor	Larry McIntire
Applicant Name	City of Evansville
Property Address	810 Taylor Avenue, Evansville, Vanderburgh, IN 47713

Image of Property

Is the entry accessible? Yes

Pre-Bid Survey Form

NOTE:

BLN is responsible only for a visual and non-intrusive inspection not involving any testing. Further inspecting, testing, sampling, and/or remediation of any conditions inspected or noted in this report remain the sole responsibility of the owner.

POTENTIAL ASBESTOS-CONTAINING MATERIALS (ACM) No

POLYCHLORINATED BIPHENYLS (PCBs)	No
Mercury light switches	No
Mercury-containing thermostats Room Attach Image	Yes Bedroom

Mercury-containing gas pressure regulators	No
Batteries Room Attach Image	Yes Hall

Fluorescent, high-intensity discharge (HID), and low pressure sodium lamp bulbs	No
Refrigerant (found in air conditioners, refrigerators, freezers and dehumidifiers)	No
Smoke detectors Room Attach Image	Yes Multiple Rooms

Fire extinguishers	No
Compressed gas cylinders	No
Electronics	Yes
Room	Multiple Rooms

Attach Image

Chemicals	Yes
Room	Hall

Attach Image

Pesticides	No

Paints	Yes
Room	Multiple Rooms
Attach Image	

Solvents	No
Used oil	No
Fuels and fuel oil tanks	No
Biological waste (vermin, pigeon excrement)	No
Medical waste (syringes)	No
Mechanical equipment (lawn mowers, etc.)	No
Scrap tires	Yes
Room	Exterior/Yard
Attach Image	

Major appliances | Yes
Room | Basement
Attach Image

Furniture | Yes
Room | Multiple Rooms
Attach Image




Mattresses	No
Controlled substances (pharmaceuticals or illegal substances)	Yes
Room	Living Room
Attach Image	

Comments

Surveyor Comments

House is two story brick and wood frame with partial vinyl siding on full basement. House is littered with trash and furniture both downstairs and upstairs. Basement is also full of junk and furniture. There is a garage in back that is full of trash and junk. The yard is littered with trash and debris. House has concrete porch with steps and lead walk. There is also a concrete driveway which currently has an old junk car setting in it. House has brick chimney which will need to be removed with caution as to not damage neighboring house.

Disclaimer/Limitation Language For Pre-Demolition Reports

This inspection report was performed on behalf of and solely for the exclusive use of the Indiana Housing And Community Development Agency ("IHCDA") and persons or organizations to whom the IHCDA wishes to make this report available. The services for this project have been performed in general conformance with the contract negotiated between IHCDA and Beam Longest & Neff ("BLN"). Any reliance on this report by a party other than IHCDA or agents of IHCDA shall be at the party's own risk. The observations set forth herein are valid only for the date and time noted herein. BLN specifically disclaims any responsibility for conditions of the subject property prior to or after the date and time set forth herein. BLN shall not be responsible for damages, consequential or otherwise, for contamination or conditions not clearly present on the day and time of the survey. The observations set forth herein are based exclusively upon a visual inspection of items and matters that are clearly visible, are outside of confined or inaccessible areas, and are identified on the checklist in the contract between IHCDA and BLN. BLN has not conducted any intrusive inspections, intrusive observations, testing or abatement of any item observed during the course of the survey or identified herein. The observations set forth in this Pre-Demolition Survey report shall not be construed as a recommendation for any specific action and shall not be construed as any form of a legal opinion.