Asbestos Inspection Summary

CES Job #	Address	Street	Regulated ACM (RACM) To Be Removed (LINFT)	Regulated ACM (RACM) To Be Removed (SQFT)	Non-Friable Asbestos Material To Be Removed (SQFT) Category I	Non-Friable Asbestos Material To Be Removed (SQFT) Category II	Non-Friable Asbestos Material Not To Be Removed (SQFT) Category I	Non-Friable Asbestos Material Not To Be Removed (SQFT) Category II	Removal Location	Material to Be Removed
118-2017	810	Taylor Ave	0.0	0.00	0.0	0.0	2,685.8	0.0	NA	NA
118-2018	204	S. Bedford Ave	0.0	0.00	0.0	0.0	1,271.3	0.0	NA	NA
118-2019	714	Line St	0.0	0.00	0.0	0.0	3,822.0	0.0	NA	NA
118-2020	442	S. Linwood Ave	0.0	0.00	0.0	0.0	1,421.7	0.0	NA	NA
118-2021	602	E. Blackford Ave	0.0	43.63	0.0	0.0	2,114.0	0.0	Basement	Duct Wrap
118-2022	209	S. Grand Ave	0.0	26.18	0.0	2,600.0	1,514.8	0.0	Living Room & Basement, Exterior Under Brick	Duct Wrap, Transite Siding
118-2023	1126	Jefferson Ave	0.0	9.68	0.0	0.0	2,177.5	0.0	Basement & Kitchen	Duct Wrap/Tape
118-2024	432	S. Evans Ave	0.0	1.40	0.0	0.0	1,949.5	0.0	Basement	Duct Wrap
118-2025	765	E. Cherry St	0.0	0.00	0.0	0.0	1,914.0	0.0	NA	NA