

Form Information

Form Name: Submission Date: IHCDA | BLN Pre-Bid Survey Results Jul 27, 2018 1:36:04 PM EDT

General Parcel Survey Information

Date of Survey Name of Surveyor Applicant Name Property Address Jul 27, 2018 Larry McIntire City of Evansville 813 E. Virginia St. Evansville, IN. 47711

Image of Property



Is the entry accessible?

Yes

Pre-Bid Survey Form

NOTE:

BLN is responsible only for a visual and non-intrusive inspection not involving any testing. Further inspecting, testing, sampling, and/or remediation of any conditions inspected or noted in this report remain the sole responsibility of the owner.

Room Attach Image

Multiple Rooms



Mercury light switches	No
Mercury-containing thermostats	Yes

Mercury-containing thermostats Room Attach Image



Mercury-containing gas pressure regulators	No	
Batteries	No	

Living Room

Fluorescent, high-intensity discharge (HID), and low pressure sodium lamp bulbs

Yes

Room

Attach Image

Multiple Rooms



Refrigerant (found in air conditioners, refrigerators, freezers Yes and dehumidifiers)

Room Attach Image Multiple Rooms



Smoke detectors Room Attach Image



Yes Bedroom

Fire extinguishers	No
Compressed gas cylinders	No

Electronics

Room

Attach Image



Chemicals Room Attach Image



Pesticides Room

Yes Kitchen

Yes

Multiple Rooms

Yes Exterior/Yard

Attach Image



Paints Room Attach Image Yes Basement



Solvents Room Attach Image



Yes Exterior/Yard

Used oil	No
Fuels and fuel oil tanks	No

Biological waste (vermin, pigeon excrement)	No	
Medical waste (syringes)	No	
Mechanical equipment (lawn mowers, etc.)	No	

Scrap tires Room

Attach Image

Yes Exterior/Yard



Major appliances Room Attach Image

Yes Multiple Rooms



Furniture Room Attach Image Yes Multiple Rooms





Mattresses Room Attach Image



Yes Multiple Rooms Controlled substances (pharmaceuticals or illegal substances)

Comments

Surveyor Comments

House is one story wood frame with some aluminum siding over asphalt shingles. There is a brick cellar and house appears to have attic space. Inside is still littered with debris and old furniture. Yard is overgrown with weeds and has piles of trash. There is a metal shed in back to be removed. The metal pole barn adjacent to house is to remain. House has concrete steps in front to be removed and lawn to be regraded. Possible cistern in backyard. Basement is filled with trash and old paint cans. Some rooms have ceiling tiles. The furnace in basement is very old and tape wrap may be ACM. Roofing appears to be metal.

9

No

Disclaimer/Limitation Language For Pre-Demolition Reports

This inspection report was performed on behalf of and solely for the exclusive use of the Indiana Housing And Community Development Agency ("IHCDA") and persons or organizations to whom the IHCDA wishes to make this report available. The services for this project have been performed in general conformance with the contract negotiated between IHCDA and Beam Longest & Neff ("BLN"). Any reliance on this report by a party other than IHCDA or agents of IHCDA shall be at the party's own risk. The observations set forth herein are valid only for the date and time noted herein. BLN specifically disclaims any responsibility for conditions of the subject property prior to or after the date and time set forth herein. BLN shall not be responsible for damages, consequential or otherwise, for contamination or conditions not clearly present on the day and time of the survey. The observations set forth herein are based exclusively upon a visual inspection of items and matters that are clearly visible, are outside of confined or inaccessible areas, and are identified on the checklist in the contract between IHCDA and BLN. BLN has not conducted any intrusive inspections, intrusive observations, testing or abatement of any item observed during the course of the survey or identified herein. The observations set forth in this Pre-Demolition Survey report shall not be construed as a recommendation for any specific action and shall not be construed as any form of a legal opinion.